

Report No. 19 CIA/PIR 75066

25X1

December 1966 DATE





#### Approved For Release 2003/03/04: CIA-RDP78T05161A001200010048-4

#### WARNING

This document contains information affecting. within the meaning of Title 18, sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law.

RECO			COPY NO.	PUB. DATE		LOCATION		MASTER		ER	DATE RECEIVED	LOCATION			
			DISPOSITI	@doffor Rei		2003/0	3/04 ·	گاگ	BDE	78T0	5161A001200010048-4	MAXIMUM	6	··········	
CUT		0	DATE 1-73	CUT TO COPIES	-03	DATE	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			STROY		<u>r</u>			
CUT COP			DATE	CUT TO COPIES		DATE					,				
CUT TO COPIES			DATE .	MASTER	DATE					•					
DATE		]			ผบผ	BER OF C	OPIES	DATE				NUMB	NUMBER OF COPIES		
₩0.	DAY	YR.	RECEIVED OR	ISSUED	REC	'D ISS'D	BAL	₩О.	DAY	YR.	RECEIVED OR ISSUED REC'E		188'	BAL	
5	22	68	Dist. Unit		6		6								
10	20	72	Dest 60	opies			0	w	gl/	6	_				
			<del>-</del>												
												_			
TITL	_	PIC		red Fo <u>p</u> Re¦	eas	<del>5/2003/(</del>	: <del>3/04)</del> رج	GIA	<del>'RDF</del>	<del>'78TC</del>	<del>)5161A00</del> 1200010048-4		`	25X1	
PIR-75066 RPT.#19 5035478 201															

DATE				NUMBER OF COPIES			DATE			RECEIVED OR ISSUED		NUMBER OF COPIES		
		YR.	RECEIVED OR ISSUED	REC'D ISS'D BAL		MO. DAY YR.					REC D	155'0	BAL	
	$\dashv$		Approved For Re	ease	2003/0	3/04	CIA	-RD	P78	T05161A0012	200010048-4			
			,											
		-		<u> </u>	<u> </u>	<u> </u>								
_	-			-								+		_
}			·			-				-		+	ļ	
	$\rightarrow$			<u> </u>					-			-	<del> </del>	
				<u> </u>						<b></b> _			ļ <u>.</u>	<b></b>
													<u> </u>	
														ļ
					ļ ·									
$\rightarrow$				<u>.                                    </u>										
				ļ								<del></del>		·
				1	<u> </u>		<u> </u>	-	<b> </b>			+		-
				ļ	ļ		<u> </u>		-		·	<del></del>	-	
				<del> </del>	<del>                                     </del>	_	<u> </u>		<del> </del>				ļ	
							<u> </u>					-	-	
			Approved For Re	 lease	2003/0	3/04	: CIA	RD	 P78	 ∏05161∆0013	200010048-4			<u> </u>
TITL	E N1	PIC	Approved For Re	.1966			S/				<u> </u>			25X <sup>2</sup>

PIR-75066 RPT #19

CIA IMAGERY ANALYSIS DIVISION

PIR 75066

25X1

#### **PREFACE**

This report summarizes significant items of photo intelligence relating to the North Vietnamese railroad system which has been developed from available photography (received by the CIA Imagery Analysis Division) during the period indicated on the cover. This report is intended to provide a comprehensive view of the railroad system and does not necessarily reflect the most recent status changes as reported by pilots' reports or field photo intelligence cables.

The railroad system has been broken down into 5 major lines: the Hanoi/Lao Cai Line, the Hanoi/Dong Dang Line, the Hanoi/Haiphong Line, the Hanoi/Dong Hoi Line and the Thai Nguyen Line (Figure I). Annotated maps and photos are used to show the status of each line.

-1-

## Approved For Release 2003/03/940RGIA-RDP78T05161A001200010048-4

PIR 75066 **25X1** FIGURE 1 NORTH VIETNAMESE RALROAD SYSTEM THANH THUY TUYEN BIEN  $T \cup S \times I S$ NONG KHAI MUANG HON PHANOM THAKHEK DEMARCATION LINE NPIC BASE 11 DONG HA NAUTICAL MILES

25X1

CIA IMAGERY ANALYSIS DIVISION


PIR 75066

#### SUMMARY

That portion of the Hanoi/Lao Cai Rail Line observed on interpretable photography is now open to through traffic with the exception of the Viet Tri crossing. The North Vietnamese continue to attempt to reopen the Hanoi/Vinh segment of the Hanoi/Dong Hoi Rail Line; 4 bridges were reopened and 2 bridges were newly interdicted. Portions of the Hanoi/Dong Dang and Hanoi/Haiphong Rail Lines covered by interpretable photography were open to through traffic.

#### CONTENTS

Hanoi/Lao Cai Rail Line	Page	4
Hanoi/Dong Dang Rail Line	3	6
Hanoi/Dong Hoi Rail Line		14
Hanoi/Haiphong Rail Line		30
Thai Nguyen Rail Line		31



## Approved For Release 2003/0 **SELRETA-RDP78T05161** A001200010048-4

PIR 75066

25X1

25X1

CIA IMAGERY ANALYSIS DIVISION

ITEM OF INTEREST NO. 1: Hanoi/Lao Cai Rail Line

NAME

: Lang Kay RR. Bridge

BE

:

COORDINATES


: 22 03N - 104 29E, VK 472394

PHOTO REFERENCE


: JOG (A) 1501, NF 48-6

MAP REFERENCE

The four-span, deck-type Lang Kay Railroad Bridge has been repaired and is serviceable.



-5-



### Approved For Release 2003/0**\$66RET**A-RDP78T05161A001200010048-4

CIA IMAGERY ANALYSIS DIVISION

PIR 75066

ITEM OF INTEREST NO. 1: Hanoi/Dong Dang Rail Line

NAME

: Construction

BE

M Δ

COORDINATES

: 21 05N - 105 55E, WJ 964320

PHOTO REFERENCE

MAP REFERENCE

: JOG (A) 1501, NF 48-11

.

DOCUMENTS


: CIA/IAD Cable, CIA-P-167

A particularly sharp set of curves on the by-pass route around the Hanoi Railroad and Highway Bridge over Canal Des Rapides is being realigned to lessen the curvature of the roadbed. This may indicate an attempt in the near future to extend dual gauge track from its present terminus at Kep (21 24N - 106 17E) toward Hanoi.

The by-pass bridge was originally observed under construction on photography dated \_\_\_\_\_\_ but it has never been completed. All

of the piers are in place, but the spans are missing.

25X1



Approved For Release 2003/03/64 PEIA-RDP78T05161A001200010048-4

25X1

25X1

25X1

#### Approved For Release 2003/0364 REIA-RDP78T05161A001200010048-4

CIA IMAGERY ANALYSIS DIVISION

PIR 75066

25X1

ITEM OF INTEREST NO. 2: Hanoi/Dong Dang Rail Line

NAME

: Dap Cau RR. and Hwy. Bridge

25X1

 $_{
m BE}$ 

25X1

: |

COORDINATES


: 21 12N - 106 05E, XJ 135450


PHOTO REFERENCE

MAP REFERENCE

: JOG (A) 1501, NF 48-11

The 80' swing span (i.e., two 40' sections) of the Dap Cau Railroad and Highway Bridge has been destroyed and one 140' deck section is out of alignment (Figure 6). The 8-span, deck-beam by-pass bridge west of the main bridge is now serviceable. One span has been temporarily removed and is located on a large raft to the west of the bridge. No attempt has been made to conceal this span. This deception technique also permits free navigation of the river, while the bridge may be used for rail traffic when it is needed. There is no evidence of dual gauge (i.e., meter and standard gauge) track in the vicinity of this river crossing.





## Approved For Release 2003/03/12-RDP78T05161A001200010048-4

CIA IMAGERY ANALYSIS DIVISION

PIR 75066

25X1

ITEM OF INTEREST NO. 3: Hanoi/Dong Dang Rail Line

NAME

: Rolling stock

BE

: NA

COORDINATES

: 21 26N - 106 20E, XJ 393707

25X1

PHOTO REFERENCE

MAP REFERENCE

: JOG (A) 1501, NF 48-11


DOCUMENTS

: NPIC Briefing Board L-2318, 28 November 1966

A three-track, dual-gauge rail yard at UTM XJ 393707 was observed at approximately 60% capacity. The rolling stock of undetermined gauge consists of approximately 48 box cars, 2 probable passenger coaches, 2 flat cars (loaded), 1 probable tank car, 1 probable gondola car, and 3 unidentified pieces of equipment. In addition, 2 gondola cars and 2 box cars are located on the track by-passing the yard.

This rail yard is located near the Kep Storage Area No. 2 (UTM XJ 390701). This storage area (partially illustrated) consists of 63 large buildings and 23 smaller storage/support structures. Twenty three of the large buildings have been constructed since

25X1



# Approved For Release 2003/03 FCRET - RDP78T05161A001200010048-4 25X1

CIA IMAGERY ANALYSIS DIVISION

PIR 75066

ITEM OF INTEREST NO. 4: Hanoi/Dong Dang Rail Line

NAME

: Train

BE

: NA

COORDINATES


: 21 28N - 106 22E, XJ 430748

PHOTO REFERENCE

MAP REFERENCE

: JOG (A) 1501, NF 48-11

A probable standard gauge train consisting of a locomotive and tender, 2 cabooses, and 13 probable canvas-covered gondola cars is stopped, facing south in a 4-track dual-gauge rail yard at UTM XJ 430748. The other 4 pieces of rolling stock in the yard are probably standard gauge flat cars.



## Approved For Release 2003/056 RETA-RDP78T05161 A001200010048-4

CIA IMAGERY ANALYSIS DIVISION

PIR 75066

ITEM OF INTEREST NO. 1: Hanoi/Dong Hoi Rail Line

NAME

: Quang Te RR. Bridge

BE

:

COORDINATES


: 18 27N - 105 34E, WF 610400

PHOTO REFERENCE

: JOG (A) 1501, NE 48-7

MAP REFERENCE

Three spans of the 5-span, deck-type Quang Te Railroad Bridge have been destroyed and both approaches have been interdicted.



-15-

25X1

25X1

### Approved For Release 2003/03/64-RDP78T05161A001200010048-4

CIA IMAGERY ANALYSIS DIVISION

PIR 75066

25X1

25X1

ITEM OF INTEREST NO. 2: Hanoi/Dong Hoi Rail Line

NAME

: Tam Da RR. and Hwy. Bridge

BE

:

COORDINATES

: 18 50N - 105 39E, WF 691839


PHOTO REFERENCE

: |

MAP REFERENCE

: JOG (A) 1501, NE 48-7

Three spans of the multi-span, deck-beam Tam Da Railroad replacement bridge have been dropped and 2 piers have been destroyed. A by-pass bridge continues under construction to the west of the main bridge.



257

25X1

Approved For Release 2003/05/64RETA-RDP78T05161A001200010048-4

CIA IMAGERY ANALYSIS DIVISION

PIR 75066

25X1

25X1

ITEM OF INTEREST NO. 3: Hanoi/Dong Hoi Rail Line

NAME

: Dien Chau RR. Bridge E By-pass No. 1

ΒE

:

COORDINATES

: 18 58N - 105 35E, WF 619980


PHOTO REFERENCE

; |

MAP REFERENCE

: JOG (A) 1501, NE 48-7

The multi-span, deck-beam Dien Chau Railroad Bridge E By-pass No. 1 has been repaired and is serviceable. The main bridge is destroyed.



25X1

-17-

## Approved For Release 2003/0 **\$6CREIA**-RDP78T05161A001200010048-4

CIA IMAGERY ANALYSIS DIVISION

PIR 75066

25X1

25X1

ITEM OF INTEREST NO. 4: Hanoi/Dong Hoi Rail Line

NAME

: Dia Thuy RR. By-pass Bridge NW

ΒE

:

25X1

COORDINATES

: 19 23N - 105 43E, WG 756418


PHOTO REFERENCE

:

MAP REFERENCE

: JOG (A) 1501, NE 48-3

The multi-span, deck-beam Dia Thuy Railroad By-pass Bridge NW has been destroyed. The main bridge remains unserviceable. Another by-pass bridge is in the initial stages of construction.



### Approved For Release 2003/646/REJIA-RDP78T05161A001200010048-4

25X1

CIA IMAGERY ANALYSIS DIVISION

PIR 75066

25X1

ITEM OF INTEREST NO. 5: Hanoi/Dong Hoi Rail Line

NAME

: Dong Phong Thuong RR. Bridge By-pass No. 1

BE

: NA

COORDINATES

: 19 58N - 105 51E, WH 890090


PHOTO REFERENCE

:

MAP REFERENCE

: JOG (A) 1501, NE 48-3

The multi-span, deck-beam Dong Phong Thuong Railroad Bridge By-pass No. 1 has been repaired and is serviceable. All other river crossings at this location are unserviceable.



-19-

#### Approved For Release 2003/0**\$/₽€ | REIA**-RDP78T05161A001200010048-4

PIR 75066
 .,

CIA IMAGERY ANALYSIS DIVISION

25X1

ITEM OF INTEREST NO. 6: Hanoi/Dong Hoi Rail Line

NAME

: Ninh Binh RR. Bridge By-pass No. 1

BE

: NA

COORDINATES

: 20 15N - 105 59E, XH 039398


25X1


PHOTO REFERENCES

MAP REFERENCE

: JOG (A) 1501, NF 48-15

Construction of the multi-span, deck-beam Ninh Binh Railroad Bridge By-pass No. 1 has been completed (inset 1), and the by-pass route on both sides of the river is serviceable. The lift span permits continued use of the river for navigation. A ferry crossing adjacent to the unserviceable Ninh Binh Railroad and Highway Bridge \_\_\_\_\_\_\_\_ at UTM XH 030405 is being modified (inset 2). The slips are being extended further into the river and may later be joined to form a second by-pass bridge. However, the presence of a rail ferry boat (inset 3) indicates that the ferry 25X1 crossing is still serviceable.





## Approved For Release 2003/03 4-RDP78T05161A001200010048-4

25X1

CIA IMAGERY ANALYSIS DIVISION

PIR 75066

ITEM OF INTEREST NO. 7: Hanoi/Dong Hoi Rail Line

NAME

: Locomotive and Tender

BE

: NA

25X1

COORDINATES

: 20 19N - 106 05E, XH 128482

PHOTO REFERENCE

MAP REFERENCE

: JOG (A) 1501, NF 48-15

A locomotive appears to have been abandoned in a 3-track rail yard at UTM XH 128482. The cab of the engine seems to be slightly twisted, and the tender is lying in a bomb crater - probably damaged beyond repair. All rail has been removed from the track on which the locomotive is resting.

SECRET<sup>A-IX</sup> PIR 75066 FIGURE 17 ABANDONED LOCOMOTIVE AND TENDER SECRET 04 : CIA-RDP7 7 705 164 A001200010048-4

## Approved For Release 2003/03 FAREIA-RDP78T05161A001200010048-4

PIR 75066

25X1

25X1

CIA IMAGERY ANALYSIS DIVISION

25X1

ITEM OF INTEREST NO. 8: Hanoi/Dong Hoi Rail Line

NAME

: Cao Duong RR. Bridge

BE

:

COORDINATES

: 20 28N - 106 02E, XH 079643


PHOTO REFERENCE

:

MAP REFERENCE

: JOG (A) 1501, NF 48-15

Both spans of the 2-span, half-through truss Cao Duong Railroad Bridge have been dropped. The pier and 1 abutment have been destroyed.



-24-

### Approved For Release 2003/0 **56 (RET**A-RDP78T05161A001200010048-4

CIA IMAGERY ANALYSIS DIVISION

PIR 75066

ITEM	OF	INTEREST	NO.	9:	Hanoi	/Dong	Hoi	Rail	Line

NAME

: Railroad By-pass Construction Activity

BE

: NA

COORDINATES

: 20 59N - 105 54E

PHOTO REFERENCE

:

MAP REFERENCE

: JOG (A) 1501, NF 48-11 and 15

Series L701, Sheets 6173I and 6174II

DOCUMENTS

Southeast Asia Activity Report, NPIC/R-381/66,

Summary No. 29

A 6.5 nm railroad by-pass is currently under construction between a point on the Hanoi/Dong Hoi Rail Line 3 nm south of Hanoi at UTM WJ 878192, and a point on the Hanoi/Haiphong Rail Line 6 nm east of Hanoi at UTM WJ 963252 (Figure 19). Initial grading has been completed along the entire rail alignment and probable ballast has been laid at both ends of the by-pass (insets 1 and 7). Two small railroad bridges are under construction at UTM WJ 982189 and 903197 (insets 2 and 3) and a railroad ferry complex on the Red River is under construction at UTM WJ 940938 (insets 4 and 6). Two ferry approaches are under construction on either bank of the river and adjacent earth scarring activity on the north bank of the river indicates additional unidentified railroad associated construction activity. A probable boat repair/construction facility is located immediately east of the southern railroad ferry approaches at UTM WJ 933215 (inset 5).

The significance of this by-pass	is that (1) it will provide a by-pass
for all North Vietnamese lines around	Hanoi and (2) it will provide an
alternate river crossing over the Red	River in addition to the critical
Hanoi Railroad and Highway River over	the Red River
immediately north of Hanoi.	

25X1

-25-

#### Approved For Release 2003/03/04 : CIA-RDP78T05161A001200010048-4

SECRET

CLA MAGERY ANALYSIS DIVISION

PER 170-066
FIGURE 19

COMPANY RESIDENCE SELECTOR

Red River - 3

RAILROAD BY-PASS CONSTRUCTION

Photo Inset-see the following pages

Roadbed Alignment

-26-


SECRET


PRESUND FOR DOLLARS 2002/02/04 - CIA DDDZ0T054C44004200040040

25X1

CIA IMAGERY ANALYSIS DIVISION

PIR 75066







-27-

## Approved For Release 2003/03 FARETA-RDP78T05161A001200010048-4

PIR 75066

CIA IMAGERY ANALYSIS DIVISION







25X1

CIA IMAGERY ANALYSIS DIVISION








-29-

## Approved For Release 2003/03 LA RDP78T05161 A001200010048-4

PIR 75066

CIA IMAGERY ANALYSIS DIVISION



-30-

Approved For Release 2003/03/04: CIA-RDP78T05161A001200010048-4 SECRET PIR 75066 FIGURE 20 2100N 10600E KEY All Maps within this report have been keyed in the following manner: \* By-pass bridge or bridges serviceable. Main bridge unserviceable. HAI DUONG All bridge crossing facilities unserviceable. ▲ By-pass bridge under construction. \_\_Original bridge has not been damaged or destroyed based on available photography. Extent of rail line covered by available, interpretable photography. item of interest. Turn to the item number within the section for further information. All intelligence developed within the reporting period is printed in red; older intelligence is printed in black. 2100N 10630E HANOI - HAIPHONG RAILROAD Railroad Streams Bridge No. & location 3 statute miles 10 HAIPHONG -31-SECRET

Approved For Release 2003/03/04: CIA-RDP78T05161A001200010048-4

#### Approved For Release 2003/03/04: CIA-RDP78T05161A001200010048-4


SECRET

PIR 75066 FIGURE 21

KEY

All Maps within this report have been keyed in the following manner:

- ★ Main bridge bombed now serviceable.
- \* By-pass bridge or bridges serviceable.
- ☐ Main bridge unserviceable.
- All bridge crossing facilities unserviceable.
- ▲ By-pass bridge under construction.
- ,\_\_Original bridge has not been damaged or destroyed based on available photography.
- Extent of rail line covered by available, interpretable photography.
- I tem of interest. Turn to the item number within the section for further information.



25X′

•

1

1

1

1

1

•

25